# Chapter 12: Phase Transformations

#### **ISSUES TO ADDRESS...**

• Transforming one phase into another takes time.



- How does the rate of transformation depend on time and temperature ?
- Is it possible to slow down transformations so that non-equilibrium structures are formed?
- Are the mechanical properties of non-equilibrium structures more desirable than equilibrium ones?

# **Phase Transformations**

#### Nucleation

- nuclei (seeds) act as templates on which crystals grow
- for nucleus to form rate of addition of atoms to nucleus must be faster than rate of loss
- once nucleated, growth proceeds until equilibrium is attained

Driving force to nucleate increases as we increase  $\Delta T$ 

- supercooling (eutectic, eutectoid)
- superheating (peritectic)

Small supercooling  $\rightarrow$  slow nucleation rate - few nuclei - large crystals

Large supercooling  $\rightarrow$  rapid nucleation rate - many nuclei - small crystals

# Solidification: Nucleation Types

- Homogeneous nucleation
  - nuclei form in the bulk of liquid metal
  - requires considerable supercooling (typically 80-300 °C)



- Heterogeneous nucleation
  - much easier since stable "nucleating surface" is already present — e.g., mold wall, impurities in liquid phase
  - only very slight supercooling (0.1-10 ° C)



#### **Homogeneous Nucleation & Energy Effects**



 $r^*$  = critical nucleus: for  $r < r^*$  nuclei shrink; for  $r > r^*$  nuclei grow (to reduce energy)

Adapted from Fig.12.2(b), Callister & Rethwisch 9e. AMSE 205 Spring '2016

$$\frac{d\Delta G}{dr} = \frac{1}{dr} \left( \frac{4}{3} \pi r^3 \Delta G_v \right) + \frac{1}{dr} \left( 4 \pi r^2 \gamma \right) = 0$$
$$r^* = -\frac{2\gamma}{\Delta G_v}$$
$$\Delta G^* = \frac{16 \pi \gamma^3}{3 \Delta {G_v}^2}$$

$$\begin{split} \Delta G_{v} &= \Delta H_{v} - T \Delta S_{v} = \Delta H_{v} - T \left(\frac{\Delta H_{v}}{T_{m}}\right) = \frac{\Delta H_{v}(T_{m} - T)}{T_{m}} = \frac{\Delta H_{v} \Delta T}{T_{m}} \\ r^{*} &= -\frac{2\gamma}{\Delta G_{v}} = -\frac{2\gamma T_{m}}{\Delta H_{v} \Delta T} \\ \Delta G^{*} &= \frac{16\pi\gamma^{3}}{3\Delta G_{v}^{2}} = \frac{16\pi\gamma^{3} T_{m}^{2}}{3\Delta H_{v}^{2} \Delta T^{2}} \end{split}$$

# Solidification



 $r^*$  = critical radius

 $\gamma$  = surface free energy

 $T_m$  = melting temperature

 $\Delta H_f$  = latent heat of solidification

 $\Delta T = T_m - T =$  supercooling

Note:  $\Delta H_f$  and  $\gamma$  are weakly dependent on  $\Delta T$ 

 $\therefore$  *r*<sup>\*</sup> decreases as  $\Delta T$  increases

For typical  $\Delta T$   $r^* \sim 10$  nm



Fig. 3.3. The effect of temperature on the critical sizes and critical free energy of three spherical nuclei. Supersaturation increases with a decreasing temperature and surface energy also varies with temperature.  $T_E > T_1 > T_2 > T_3$  with  $T_E$  being the equilibrium temperature.

# **Nucleation Kinetics**

The number of stable nuclei having radii greater than r\*  $n^* = K_1 \exp\left(-\frac{\Delta G^*}{kT}\right)$ 

Frequency of atoms jumping to the surface of nuclei

$$v_{\rm d} = K_2 \exp\left(-\frac{Q_d}{kT}\right)$$

Final nucleation rate

$$\dot{N} = K_3 n^* v_d exp\left(-\frac{\Delta G^*}{kT}\right) exp\left(-\frac{Q_d}{kT}\right)$$



 $v_{\rm d}$ 

n×

## **Heterogeneous Nucleation**



Surface or interface



# **Rate of Phase Transformations**

Kinetics - study of reaction rates of phase transformations

- To determine reaction rate measure degree of transformation as function of time (while holding temp constant)
  - How is degree of transformation measured?
    - X-ray diffraction many specimens required
    - electrical conductivity measurements on single specimen
    - measure propagation of sound waves on single specimen



# **Rate of Phase Transformation**

The kinetics of recrystallization for some alloys obey the JMA equation and the Avrami exponent, n, is 3.1. If the fraction of recrystallized is 0.3 after 20 min, determine the rate of recrystallization.

$$x = 1 - \exp(-kt^{n})$$

$$ln(1-x) = -kt^{n} \quad k = -\frac{\ln(1-x)}{t^{n}}$$

$$k = -\frac{\ln(1-0.3)}{(20 \text{ min})^{n}} = 3.3x10^{-5}$$

$$t^{n} = -\frac{\ln(1-x)}{k}$$

$$t = -\left[\frac{\ln(1-x)}{k}\right]^{\frac{1}{n}}$$

$$t_{0.5} = -\left[\frac{\ln(1-0.5)}{3.3x10^{-5}}\right]^{\frac{1}{3.1}} = 24.8 \text{ min}$$

$$rate = \frac{1}{t_{0.5}} = \frac{1}{24.8 \text{ min}} = 4.0x10^{-2} (\text{min})^{-1}$$

AMSE 205 Spring '2016

## Temperature Dependence of Transformation Rate



Fig. 12.11, *Callister & Rethwisch 9e.* (Reprinted with permission from *Metallurgical Transactions*, Vol. 188, 1950, a publication of The Metallurgical Society of AIME, Warrendale, PA. Adapted from B. F. Decker and D. Harker, "Recrystallization in Rolled Copper," Trans. AIME, 188, 1950, p. 888.)

• For the recrystallization of Cu, since

 $rate = 1/t_{0.5}$ 

rate increases with increasing temperature

Rate often so slow that attainment of equilibrium state not possible!

#### **Transformations & Undercooling**

- Eutectoid transf. (Fe-Fe<sub>3</sub>C system):
- For transf. to occur, must 0.7 cool to below 727 °C (i.e., must "undercool")





Fig. 11.23, Callister & Rethwisch 9e. [Adapted from Binary Alloy Phase Diagrams, 2nd edition, Vol. 1, T. B. Massalski (Editor-in-Chief), 1990. Reprinted by permission of ASM International, Materials Park, OH.]

AMSE 205 Spring '2016

### **The Fe-Fe<sub>3</sub>C Eutectoid Transformation**

• Transformation of austenite to pearlite:



Coarse pearlite  $\rightarrow$  formed at higher temperatures – relatively soft Fine pearlite  $\rightarrow$  formed at lower temperatures – relatively hard

#### Generation of Isothermal Transformation Diagrams

Consider:

- The Fe-Fe<sub>3</sub>C system, for  $C_0 = 0.76$  wt% C
- A transformation temperature of 675 °C.



Fig. 12.13, *Callister & Rethwisch 9e*. [Adapted from H. Boyer (Editor), Atlas of Isothermal Transformation and Cooling Transformation Diagrams, 1977. Reproduced by permission of ASM International, Materials Park, OH.]

#### **Austenite-to-Pearlite Isothermal Transformation**

- Eutectoid composition,  $C_0 = 0.76$  wt% C
- Begin at *T* > 727° C
- Rapidly cool to 625 °C
- Hold T (625 °C) constant (isothermal treatment)



# **Transformations Involving Noneutectoid Compositions**

Consider  $C_0 = 1.13$  wt% C



Hypereutectoid composition – proeutectoid cementite

AMSE 205 Spring '2016

# **Bainite: Another Fe-Fe<sub>3</sub>C Transformation Product**

- Bainite:
  - -- elongated Fe<sub>3</sub>C particles in *α*-ferrite matrix
  - -- diffusion controlled
- Isothermal Transf. Diagram,





#### 5μm

Fig. 12.17, *Callister & Rethwisch 9e.* (From *Metals Handbook*, Vol. 8, 8th edition, *Metallography, Structures and Phase Diagrams*, 1973. Reproduced by permission of ASM International, Materials Park, OH.)

Fig. 12.18, *Callister & Rethwisch 9e.* [Adapted from H. Boyer (Editor), *Atlas of Isothermal Transformation and Cooling Transformation Diagrams*, 1977. Reproduced by permission of ASM International, Materials Park, OH.]

# Spheroidite: Another Microstructure for the Fe-Fe<sub>3</sub>C System

- Spheroidite:
  - -- Fe<sub>3</sub>C particles within an  $\alpha$ -ferrite matrix
  - -- formation requires diffusion
  - -- heat bainite or pearlite at temperature just below eutectoid for long times
  - -- driving force -- reduction

of  $\alpha$ -ferrite/Fe<sub>3</sub>C interfacial area



#### 60 µm

Fig. 12.19, *Callister & Rethwisch 9e.* (Copyright United States Steel Corporation, 1971.)

## Martensite: A Nonequilibrium Transformation Product

- Martensite:
  - --  $\gamma$ (FCC) to Martensite (BCT)



• Isothermal Transf. Diagram





# Martensite needles Austenite

Fig. 12.21, *Callister & Rethwisch 9e.* (Courtesy United States Steel Corporation.)

- $\gamma$  to martensite (M) transformation.
  - -- is rapid! (diffusionless)
  - -- % transformation depends only on *T* to which rapidly cooled

# **Martensite Formation**



#### Martensite (M) – single phase – has body centered tetragonal (BCT) crystal structure

Diffusionless transformation BCT if  $C_0 > 0.15$  wt% C

BCT  $\rightarrow$  few slip planes  $\rightarrow$  hard, brittle

# **Phase Transformations of Alloys**

Effect of adding other elements Change transition temp.

Cr, Ni, Mo, Si, Mn retard  $\gamma \rightarrow \alpha$  + Fe<sub>3</sub>C reaction (and formation of pearlite, bainite)

> Fig. 12.23, *Callister & Rethwisch 9e.* [Adapted from H. Boyer (Editor), *Atlas of Isothermal Transformation and Cooling Transformation Diagrams*, 1977. Reproduced by permission of ASM International, Materials Park, OH.]



## **Continuous Cooling Transformation Diagrams**

Conversion of isothermal transformation diagram to continuous cooling transformation diagram



Fig. 12.25, *Callister & Rethwisch 9e.* [Adapted from H. Boyer (Editor), *Atlas of Isothermal Transformation and Cooling Transformation Diagrams*, 1977. Reproduced by permission of ASM International, Materials Park, OH.]

## Isothermal Heat Treatment Example Problems

On the isothermal transformation diagram for a 0.45 wt% C, Fe-C alloy, sketch and label the time-temperature paths to produce the following microstructures:

- a) 42% proeutectoid ferrite and 58% coarse pearlite
- b) 50% fine pearlite and 50% bainite
- c) 100% martensite
- d) 50% martensite and 50% austenite

## Solution to Part (a) of Example Problem

a) 42% proeutectoid ferrite and 58% coarse pearlite



Chapter 12 - 26

### Solution to Part (b) of Example **Problem**



AMSE 205 Spring '2016

### Solutions to Parts (c) & (d) of Example **Problem**

- c) 100% martensite rapidly quench to room temperature
- d) 50% martensite & 50% austenite
  - -- rapidly quench to ~  $290^{\circ}$  C, hold at this temperature



#### **Mechanical Props: Influence of C Content**



• Increase C content: TS and YS increase, %EL decreases

#### Mechanical Props: Fine Pearlite vs. Coarse Pearlite vs. Spheroidite



- Hardness: fine > coarse > spheroidite
- %RA: fine < coarse < spheroidite

Fig. 12.30, *Callister & Rethwisch 9e.* [Data taken from *Metals Handbook: Heat Treating*, Vol. 4, 9th edition, V. Masseria (Managing Editor), 1981. Reproduced by permission of ASM International, Materials Park, OH.]

#### Mechanical Props: Fine Pearlite vs. Martensite



Adapted from Edgar C. Bain, Functions of the Alloying Elements in Steel, 1939; and R. A. Grange, C. R. Hribal, and L. F. Porter, Metall. Trans. A, Vol. 8A. Reproduced by permission of ASM International, Materials Park, OH.

• Hardness: fine pearlite << martensite.

# **Tempered Martensite**

Heat treat martensite to form tempered martensite

- tempered martensite less brittle than martensite
- tempering reduces internal stresses caused by quenching TS(MPa)



Figure 12.33, *Callister & Rethwisch 9e.* (Copyright 1971 by United States Steel Corporation.)

- tempering produces extremely small  $Fe_3^{\prime}C$  particles surrounded by  $\alpha$ .
- tempering decreases TS, YS but increases %RA

AMSE 205 Spring '2016

## **Shape Memory Alloy** Nitinol: (Ni-Ti Naval Ordnance Laboratory)



Photograph courtesy the Naval Surface Warfare Center (previously the Naval Ordnance Laboratory



## **Shape Memory Effect**





Fig. 2. The schematic illustration of

AMSE 205 Spring '2016

shape memory effect mechanism. -

## **Pseudo Elasticity (Super Elasticity)**



Fig. 3. The schematic illustration of pseudoelastic effect.

AMSE 205 Spring '2016

#### Summary of Possible Transformations

