CHE302 LECTURE VIII DYNAMIC BEHAVIORS OF CLOSEDLOOP CONTOL SYSTEMS

Professor Dae Ryook Yang

Fall 2001 Dept. of Chemical and Biological Engineering Korea University

CHE302 Process Dynamics and Control

Korea University

8-1

8-2

Individual TF of the standard block diagram


- TF of each block between input and output of that block
- Each gain will have different unit.
 - [Example] Sensor TF
 - Inputrange: 0 -50l/min



• Outputrange: 4 - 20 mA

Gain,
$$K_m = \frac{20-4}{50-0} = 0.32 [\text{mA/(l/min)}]$$

- Dynamics: usually 1st order with small time constant $G_m(s) = \frac{G_m(s)}{t_m s} + \frac{G_m(s)}{s}$
- Block diagram shows the flow of signal and the connections
- Schematicdiagram shows the physical components connection




CHE302 Process Dynamics and Control

Korea University 8-3

BLOCK DIAGRAM REPRESENTATION

Standard block diagram of a feedback control system




- Process TF: MV (M) effect on CV (X,, part of Y)
- Load TF: DV (L) effect on CV (X₁, part of Y)
- Sensor TF: CV (Y) is transferred to measurement (B)
- Actuator TF: Controller output (P) is transferred to MV (M)
- Controller TF: Controller output (P) is calculated based on error (E)
- Calibration TF: Gain of sensor TF, used to match the actual var.


P&ID

Piping and Instrumentation diagram

- A P&ID is a blueprint, or map, of a process.
- Technicians use P&IDs the same way an architect uses blueprints.
- A P&ID shows each of the instruments in a process, their functions, their relationship to other components in the system.
- Most diagrams use a standard format, such as the one developed by ISA (Instrumental Society of America) or SAMA (Scientific Apparatus Makers Association).

CHE302 Process Dynamics and Control





Common connecting lines					
Connectiontoprocess, or instrument supply:					
Pneumatic signal:	-// //				
Electric signal:					
Capillarytubing(filledsystem):	- X X X				
Hydraulic signal:	- 				
Electromagneticorsonicsignal (guided):					
Internal system link (software or data link):	-0-0-0-0-				
Source: Control Engineering with data from	ISA S5.1 standard				

CHE302 Process Dynamics and Control

Korea University

8-5


П	Identification letters						
-	First letter		Succeedingletters				
4	Measured or initiating var.	Modifier	Readoutorpassive func.	Outputfunction	Modifier		
\	Analysis		Alarm				
3	Burner, combustion		User's choice	User's choice	User's choice		
С	User's choice			Control			
D	User's choice	Differential					
E	Voltage		Sensor(primaryelement)				
F	Flowrate	Ration(fraction)					
G	User's choice		Glass, viewing device				
н	Hand				High		
ı	Current(electrical)		Indication				
J	Power	Scan					
ĸ	Time, time schedule	Timerateof		Control station			
L	Level	change	Light		Low		
М	User's choice	Momentary			Middle, interm .		
N	User's choice		User's choice	User's choice	User's choice		
0	User's choice		Orifice, restriction				
Р	Pressure, vacuum		Point (test connection)				
Q	Quantity	Integrate, totalizer					
R	Radiation		Record				
s	Speed, frequency	Safety		Switch			
т	Temperature			Transmit			
U	Multivariable		Multifunction	Multifunction	Multifunction		
v	Vibration, mechanical analysis			Valve,damper,louver			
w	Weight, force		Well				
x	Unclassified	Xaxis	Unclassified	Unclassified	Unclassified		
Y	Event, state, or presence	Yaxis		Relay,compute,convert			
z	Position, dimension	Zaxis		Driver.actuator			

CHE302 Process Dynamics and Control

Korea University

General instrument or function symbols							
	Primary location accessible to operator	Field mounted	Auxiliary location accessible to operator				
Discrete instruments	, H	O	·				
Shared display, shared control	·⊟	, D	'B				
Computer function	Ğ	*O	, e				
Programmablelogic control	10	"[12				

- Symbol size may vary according to the user's needs and the type of document.
 Abbreviations of the user's choice may be used when necessary to specify location.
 Inaccessible (behind the panel) devices may be depicted using the same symbol but with a dashed horizontal bar. Source: Control Engineering with data from ISA S5.1 standard




8-6

6.3 GENERAL INSTRUMENT OR FUNCTION SYMBOLS (Contd.)




- * It is not mandatory to show a common housing.
- ** These diamonds are approximately half the size of the larger ones.
- 6.4 CONTROL VALVE BODY SYMBOLS, DAMPER SYMBOLS



Further information may be added adjacent to the body symbol either by

CHE302 Process Dynamics and Control

6.5 ACTUATOR SYMBOLS



Korea University

Korea University 8-10

8-9

• For set-point change (L=0)

$$\frac{Y(s)}{R(s)} = \frac{K_m G_p(s) G_v(s) G_v(s)}{1 + G_m(s) G_p(s) G_v(s) G_v(s)}$$

For load change (R=0)

$$\frac{Y(s)}{L(s)} = \frac{G_L(s)}{1 + G_m(s)G_p(s)G_v(s)G_v(s)}$$

Open-loop transfer function (G_{OL})

$$G_{OL}(s) \triangleq G_m(s)G_p(s)G(s)G(s)$$

- Feedforward path: Path with no connection backward
- Feedback path: Path with circular connection loop
- $-G_{OL}$: feedback loop is broken before the comparator
- Simultaneous change of set point and load


$$Y(s) = \frac{K_m G_p(s) G_v(s) G_v(s)}{1 + G_{OL}(s)} R(s) + \frac{G_L(s)}{1 + G_{OL}(s)} L(s)$$

CHE302 Process Dynamics and Control

Korea University 8-11

CLOSED LOOP TRANSFER FUNCTION

• Block diagram algebra



Transfer functions of closed-loop system

$$X_2(s) = G_p(s) G_p(s) G_p(s) E(s)$$
 $E(s) = K_m(s) R(s) - G_m(s) Y(s)$
 $Y(s) = G_p(s) L(s) + X_2(s)$ \longrightarrow $Y(s) = G_p(s) L(s) + G_p(s) G_p(s) E(s)$

$$Y(s) = G_L(s)L(s) + G_p(s) G(s) G(s) G(k_m(s)R(s) - G_m(s) Y(s))$$

$$\longrightarrow (1 + G_m(s)G_p(s) G(s) G(s))Y(s) = G_L(s)L(s) + K_m G_p(s) G_p(s) G_c(s) R(s)$$

MASON'S RULE

· General expression for feedback control systems

$$\frac{Y}{X} = \frac{\boldsymbol{p}_f}{1 + \boldsymbol{p}_e}$$

 $p_f \equiv \text{product of the transfer function in the path from X to Y}$

 $p_e \equiv$ product of all transfer function in the entire feedback loop

- $\quad Assume feedback \, loop \, has \, negative feedback.$
- If it has positive feedback, $1+p_e$ should be $1-p_e$.
- In the previous example, for set-pointchange

$$X = R Y = Y \mathbf{p}_{f} = K_{m}G_{c}(s)G_{v}(s)G_{p}(s) \mathbf{p}_{e} = G_{OL}(s)$$


$$\frac{Y(s)}{R(s)} = \frac{K_{m}G_{p}(s)G_{v}(s)G_{c}(s)}{1 + G_{OL}(s)}$$

- For load change, X = L Y = Y $\boldsymbol{p}_f = G_L(s)$ $\boldsymbol{p}_e = G_{OL}(s)$

CHE302 Process Dynamics and Control

Korea University 8-12

Example 1



- **Innerloop:** $X_2 = \frac{G_1 G_{c2}}{1 + G_1 \cdot G \cdot G_1}$

TF between R and Y:

$$\begin{aligned} & \boldsymbol{p}_{f} = K_{m1}G_{3}G_{2}\frac{G_{1}G_{e2}}{1 + G_{m2}G_{1}G_{c2}}G_{c1} & \boldsymbol{p}_{e} = G_{m1}G_{3}G_{2}\frac{G_{1}G_{c2}}{1 + G_{m2}G_{1}G_{c2}}G_{d} \\ & \frac{Y}{R} = \frac{K_{m1}G_{3}G_{2}G_{1}G_{2}G_{c1}}{1 + G_{m2}G_{1}G_{2}G_{c1}}G_{d} \end{aligned}$$

- TF between L₁ and Y:

$$\frac{Y}{L_1} = \frac{G_3 G_2}{1 + G_{m_2} G_1 G_{c_2} + G_{m_1} G_2 G_2 G_3 G_{c_2}}$$

CHE302 Process Dynamics and Control

Korea University 8-13

PID CONTROLLER REVISITED

P control

$$p(t) = \overline{p} + K_c e(t) \xrightarrow{\perp} \frac{P(s)}{E(s)} = K_c$$

Pl control

$$p(t) = \overline{p} + K_c \left\{ e(t) + \frac{1}{t_I} \int_0^t e(t) dt \right\} \xrightarrow{\quad L \quad} \frac{P(s)}{E(s)} = K_c (1 + \frac{1}{t_I s}) = K_c \frac{(t_I s + 1)}{t_I s}$$

PID control

$$p(t) = \overline{p} + K_c \left\{ e(t) + \frac{1}{t_I} \int_0^t e(t) dt + t_D \frac{de}{dt} \right\} \xrightarrow{\square}$$


$$\frac{P(s)}{E(s)} = K_c (1 + \frac{1}{t_I s} + t_D s) = K_c \frac{(t_I t_D s^2 + t_I s + 1)}{t_I s}$$

- Ideal PID controller: Physically unrealizable
- Modified form has to be used.

CHE302 Process Dynamics and Control

Korea University 8-15

Example 2



$$E = R - (G_1 - G_2)M = R - G_1M + G_2M$$

- Innerloop: $M = \frac{G_c}{1 G_c G} X_1$
- TF between R and Y:

$$\mathbf{p}_{f} = \frac{G_{c}}{1 - G_{2}G_{c}}G_{1} \qquad \mathbf{p}_{e} = \frac{G_{c}}{1 - G_{2}G_{c}}G_{1}$$

$$\frac{Y}{R} = \frac{G_{1}G_{c}}{1 - G_{2}G + G_{1}G} = \frac{G_{1}G_{c}}{1 + (G_{1} - G_{2})G}$$

- **TF** between L and Y: $\frac{Y}{L} = \frac{1 - G_2 G_c}{1 - G_2 G_c + G_1 G_c} = \frac{1 - G_2 G_c}{1 + (G_1 - G_2)G_c}$

Nonideal PID controller

Interactingtype

CHE302 Process Dynamics and Control

$$G_c^*(s) = K_c^* \frac{(\boldsymbol{t}_D^* s + 1)}{\boldsymbol{t}_D^* s} \frac{(\boldsymbol{t}_D^* s + 1)}{(\boldsymbol{b} \boldsymbol{t}_D^* s + 1)} \underbrace{(0 < \boldsymbol{b} \ll 1)}_{\text{Filteringeffect}}$$

Comparison with ideal PID except filter

$$G_{c}(s) = K_{c} \frac{(t_{I}t_{D}s^{2} + t_{I}s + 1)}{t_{I}s}$$


$$K_{c}^{*} \frac{(t_{D}^{*}t_{I}^{*}s^{2} + (t_{I}^{*} + t_{D}^{*})s + 1)}{t_{I}^{*}s} = \frac{K_{c}^{*}(t_{I}^{*} + t_{D}^{*})}{t_{I}^{*}} \left(1 + \frac{1}{(t_{I}^{*} + t_{D}^{*})} \frac{1}{s} + \frac{t_{D}^{*}t_{I}^{*}}{(t_{I}^{*} + t_{D}^{*})}s\right)$$

$$K_{c} = \frac{K_{c}^{*}(t_{I}^{*} + t_{D}^{*})}{t_{I}^{*}}, \quad t_{I} = t_{I}^{*} + t_{D}^{*}, \quad t_{D} = \frac{t_{D}^{*}t_{I}^{*}}{(t_{I}^{*} + t_{D}^{*})}$$

- These types are physically realizable and the modification provides the prefiltering of the error signal.
- Generally, $t_1 \ge t_D$ and typically $t_1 \approx 4t_D$.
- In this form, $t_I \ge t_D$ is satisfied automatically since algebraic mean is not less than logarithm mean.

Block diagram of PID controller

Nonideal interacting type PID



$$P(s) = K_c \frac{(\boldsymbol{t}_I s + 1)}{\boldsymbol{t}_I s} \frac{(\boldsymbol{t}_D s + 1)}{(\boldsymbol{b} \boldsymbol{t}_D s + 1)} E(s)$$

Removal of derivative kick (PI-D controller)

$$P(s) = K_c \left[\frac{(t_I s + 1)}{t_I s} \frac{(t_D s + 1)}{(b t_D s + 1)} Y(s) - \frac{(t_I s + 1)}{t_I s} R(s) \right]$$

Removal of both P & D kicks (I-PD controller)

$$P(s) = K_c \left[\frac{(\boldsymbol{t}_I s + 1)}{\boldsymbol{t}_I s} \frac{(\boldsymbol{t}_D s + 1)}{(\boldsymbol{b} \boldsymbol{t}_D s + 1)} Y(s) - \frac{1}{\boldsymbol{t}_I s} R(s) \right]$$

CHE302 Process Dynamics and Control

Korea University 8-17

DIGITAL PID CONTROLLER

Discrete time system

- Measurements and actions are taken at every sampling interval.
- An action will be hold during the sampling interval.

Digital PID controller

- **using**
$$\int_{0}^{t_{n}} e(t) dt = \Delta t \sum_{i=0}^{n} e(t_{i}) \text{ (Rectangular rule)}$$

$$\frac{d e(t)}{dt} = \frac{e(t_{n}) - e(t_{n-1})}{\Delta t} \text{ (Backward difference approx.)}$$

$$p(t_{n}) = \overline{p} + K_{c} \left[e(t_{n}) + \frac{\Delta t}{t_{I}} \sum_{i=0}^{n} e(t_{i}) + t_{D} \frac{e(t_{n}) - e(t_{n-1})}{\Delta t} \right] \text{ (Position form)}$$

$$\Delta p(t_{n}) = p(t_{n}) - p(t_{n-1})$$

 $=K_{c}\left[e(t_{n})-e(t_{n-1})+\frac{\Delta t}{t} e(t_{n})+t_{D}\frac{e(t_{n})-2e(t_{n-1})+e(t_{n-2})}{\Delta t}\right] \text{ (Velocity form)}$

CHE302 Process Dynamics and Control

Korea University 8-19

Other variations of PID controller

- Gain scheduling: modifying proportional gain

$$K_c^{GS} = K_c K^{GS}$$

1.
$$K^{GS} = \begin{cases} K_{Gap} & \text{for (lower gap)} \le e(t) \le (\text{upper gap}) \\ 1 & \text{otherwise} \end{cases}$$

2.
$$K^{GS} = 1 + C_{GS} |e(t)|$$

3. K^{GS} is decided based on some strategy

Nonlinear PID controller

- Replace e(t) with e(t) | e(t) |.
- Sign of error will be preserved but small error gets smaller and larger error gets larger.
- It imposes less action for a small error.

- Most modern PID controllers are manufactured in digital form with short sampling time.
- If the sampling time is small, there is not much difference between continuous and digital forms.
- Velocity form does not have reset windup problem because there is no summation (integration).
- Other approximation such as trapezoidal rule and etc. can be used to enhance the accuracy. But the improvement is not substantial.

$$\int_{0}^{t_{n}} e(\mathbf{t}) d\mathbf{t} = \Delta t \sum_{i=1}^{n} \frac{e(t_{i}) - e(t_{i-1})}{2}$$
 (Trapezoidal rule)
$$\frac{de(t)}{dt} = \frac{e(t_{n}) + 3e(t_{n-1}) - 3e(t_{n-2}) - e(t_{n-3})}{\Delta t}$$
 (Interpolation formula)

 For discrete time system, z-transform is the counterpart of Laplace transform. (out of scope of this lecture)


CLOSED-LOOP RESPONSE OF 1ST ORDER SYSTEM

Process

$$\mathbf{r}A\frac{dh}{dt} = \mathbf{r}q_1 + \mathbf{r}q_2 - \mathbf{r}\frac{h}{R}$$

$$G_p(s) = \frac{H(s)}{Q_2(s)} = \frac{R}{RAs+1} = \frac{K_p}{\mathbf{t}s+1}$$

$$G_L(s) = \frac{H(s)}{Q_1(s)} = \frac{R}{RAs+1} = \frac{K_p}{\mathbf{t}s+1}$$




Assume

Sensor and actuator dynamics are fast enough to be ignored and gains are lumped in other TF.

$$G_{\nu}(s) = G_{m}(s) = 1$$

$$G G$$

$$H(s) = \frac{G_c G_p}{1 + G_c G_p} R(s) + \frac{G_L}{1 + G_c G_p} L(s)$$



CHE302 Process Dynamics and Control

Korea University 8-21

P control for load change (R=0)

$$G_c(s) = K_c \quad (K_c > 0)$$


$$G_{CL}(s) = \frac{H(s)}{L(s)} = \frac{K_p / (ts+1)}{1 + K_c K_p / (ts+1)} = \frac{K_p / (1 + K_c K_p)}{(t / (1 + K_c K_p))s + 1}$$
 (closed-loop TF)

Closed-loop gain and time constant

$$K_{CL} = \frac{K_p}{(1 + K_c K_p)}, \quad \mathbf{t}_{CL} = \frac{\mathbf{t}}{(1 + K_c K_p)}$$

- Steady-state behavior of closed-loop system

$$K_{CL} = \frac{K_p}{(1 + K_c K_p)} > 0$$
, $\lim_{K_c \to \infty} G_{CL} = 0$ (disturbance is compensated)



Steady-state offset = $0 - h(\infty) = 0 - K_{CL} = -\frac{K_p}{1 + K_c K}$

Disturbance effect will not be eliminated completely (offset)

Infinite controller gain will eliminate the offset

Higher controller gain results faster closed -loop response: shorter time constant

CHE302 Process Dynamics and Control

Korea University 8-23

P control for set-point change (L=0)

$$G_c(s) = K_c \quad (K_c > 0)$$


$$G_{CL}(s) = \frac{H(s)}{R(s)} = \frac{K_c K_p / (t + 1)}{1 + K_c K_p / (t + 1)} = \frac{K_c K_p / (1 + K_c K_p)}{(t / (1 + K_c K_p))s + 1}$$
 (closed-loop TF)

Closed-loop gain and time constant

$$K_{CL} = \frac{K_c K_p}{(1 + K_c K_p)}, \quad \mathbf{t}_{CL} = \frac{\mathbf{t}}{(1 + K_c K_p)}$$

Steady-state behavior of closed-loop system

$$K_{CL} = \frac{K_c K_p}{(1 + K_c K_p)} < 1$$
, $\lim_{K_c \to \infty} G_{CL} = 1$ ($H(s) = R(s)$, no offset)



Steady-state offset = $r(\infty) - h(\infty) = 1 - K_{CL} = \frac{1}{1 + K_{CK}}$

Closed-loop response will not reach to set point (offset)

Infinite controller gain will eliminate the offset

Higher controller gain results faster closed -loop

response: shorter time constant

CHE302 Process Dynamics and Control

Korea University 8-22

PI control for load change (R=0)

$$G_a(s) = K_a(t_1 s + 1)/t_1 s \quad (K_a > 0)$$


$$G_{CL}(s) = \frac{K_p / (t + 1)}{1 + K_c K_p (t_I s + 1) / (t s + 1) / t_I s} = \frac{K_p t_I s}{t_I t s^2 + t_I (1 + K_c K_p) s + K_c K_p}$$


- Closed-loop gain, time constant, damping coefficient

$$K_{CL} = \frac{\mathbf{t}_{I}}{K_{c}}, \quad \mathbf{t}_{CL} = \sqrt{\frac{\mathbf{t}\mathbf{t}_{I}}{K_{c}K_{p}}}, \quad \mathbf{z}_{CL} = \frac{1}{2} \frac{(1 + K_{c}K_{p})}{\sqrt{K_{c}K_{p}}} \sqrt{\mathbf{t}_{I}/\mathbf{t}}$$

Steady-state behavior of closed-loop system

 $\lim G_{CL}(s) = 0$ (disturbance is compensated for all cases)





- As K₁ increases, faster compensation of disturbance and less oscillatory response can be achieved.
- As t_I decreases, faster compensation of disturbance and less overshooting response can be achieved.
- However, usually the response gets more oscillation as K_a increases or t_i decreases. => very unusual!!
- If there is small lag in sensor/actuator TF or time delay in process TF, the system becomes higher order and these anomalous results will not occur. These results is only possible for very simple process such as 1st ordersystem.
- Usual effect of PID tuning parameters
 - As K increases, the response will be faster, more oscillatory.
 - As t_1 decreases, the response will be faster, more oscillatory.
 - As t_D increases, the response will be faster, less oscillatory when there is no noise.

CHE302 Process Dynamics and Control

Korea University 8-25

P control for set-point change (L=0)

$$G_c(s) = K_c \quad (K_c < 0)$$

$$G_{CL}(s) = \frac{H(s)}{R(s)} = \frac{K_c/(-As)}{1+K_c/(-As)} = \frac{1}{(-A/K_c)s+1}$$
 (closed-loop TF)

- Closed-loop gain and time constant

$$K_{CL} = 1$$
, $t_{CL} = -A/K_{CL}$

Steady-state behavior of closed-loop system

$$K_{CL} = 1$$
 (H(s) = R(s), no offset even with p control)

- It is very unique that the integrating system will not have offset even with P control for the set point change.
- Even though there are other dynamics in sensor or actuator. the offset will not be shown with P control for integrating systems.
- Higher controller gain results faster closed loop response: shorter time constant

CHE302 Process Dynamics and Control

Korea University 8-27


CLOSED-LOOP RESPONSE OF INTEGRATING SYSTEM

Process

$$\mathbf{r}A\frac{dh}{dt} = \mathbf{r}(q_1 + q_2) - \mathbf{r}q_3$$

$$G_p(s) = \frac{H(s)}{Q_3(s)} = -\frac{1}{As}$$

$$G_L(s) = \frac{H(s)}{O_1(s)} = \frac{1}{As}$$




Assume

Sensor and actuator dynamics are fast enough to be ignored and gains are lumped in other TF.

$$G_{v}(s) = G_{m}(s) = 1$$

$$H(s) = \frac{G_{c}G_{p}}{1 + G_{c}G_{p}}R(s) + \frac{G_{L}}{1 + G_{c}G_{p}}L(s)$$



P control for load change (R=0)

$$G_{a}(s) = K_{a} \quad (K_{a} < 0)$$

$$G_{CL}(s) = \frac{H(s)}{L(s)} = \frac{1/(As)}{1+K/(-As)} = \frac{-1/K_c}{(-A/K)s+1}$$
 (closed-loop TF)

Closed-loop gain and time constant

$$K_{CI} = (-1/K_c), \quad t_{CI} = -A/K_c$$

Steady-state behavior of closed-loop system

$$K_{CL} = \frac{1}{(-K_c)} > 0$$
, $\lim_{K_c \to \infty} G_{CL} = 0$ (disturbance is compensated)

- Higher controller gain results faster closed loop response: shorter time constant

• PI control for set-point change (L=0)

$$G_c(s) = K_c(t_1 s + 1)/t_1 s$$
 $(K_c < 0)$

$$G_{CL}(s) = \frac{K_c(t_I s + 1)/(-As)/t_I s}{1 + K_c(t_I s + 1)/(-As)/t_I s} = \frac{(t_I s + 1)}{(-t_I A/K_c)s^2 + t_I s + 1}$$

- Closed-loop gain, time constant, damping coefficient

$$K_{CL} = 1$$
, $\mathbf{t}_{CL} = \sqrt{-\frac{\mathbf{t}_I A}{K_c}}$, $\mathbf{z}_{CL} = \frac{1}{2} \sqrt{-\frac{\mathbf{t}_I K_c}{A}}$

Steady-state behavior of closed-loop system

$$K_{CL} = \lim_{s \to 0} G_{CL}(s) = 1 \ (H(s) = R(s), \text{ no offset})$$

- As $(-K_c)$ increases, closed-loop time constant gets smaller (faster response) and less oscillatory response can be achieved.
- As t_1 decreases, closed-loop time constant gets smaller (faster response) and more oscillatory response can be achieved.
- Partly anomalous results due to integrating nature
- For integrating system, the effect of tuning parameters can be different. Thus, rules of thumb cannot be applied blindly.

CHE302 Process Dynamics and Control

Korea University 8-29

